6.12 The Cooley-Tukey's butterfly is shown to the right. A complex multiplication can be written in terms of real multiplications

$$(a + j\,b)(c + j\,d) = (ac - bd) + j(ad + bc)$$

Propagation of the 26 shimming delays gives the result shown below. 50 D-elements are required.